

**IMPORTANT NOTICE REGARDING  
CARBON MONOXIDE ALARMS  
FROM THE MILLBURY FIRE DEPT**

Carbon Monoxide Detectors have a lifespan of 5 to 7 years. When a detector reaches the “end of life”, it will sound an alarm. When this happens, there is no way of resetting them and the detectors will no longer sense carbon monoxide.

As part of “Nicole’s Law” passed in 2006, all homes are required to have carbon monoxide detectors on every level (unless there is nothing using fossil fuels in the house). Carbon monoxide is known as the *odorless killer* because it has no color, taste or odor.

If your detector does alarm, do not disregard it, still call the fire dept to verify there is none present.

**We are asking residents to be proactive and check the date of their detector, and possibly replace it before this occurs.**

Thank you for helping us with this important issue. If have any questions call the Fire Dept business office at 508-865-5328.